



Spa Maintenance

Start Up

- Add 2oz. of Stain & Scale Control while spa is filling
- Place 3 Chlorine Tablets in Chlorinator

After 24 Hours

- Rinse filter with garden hose
- Check and adjust PH between 7.4-7.6
- Add Bioguard Enhanced Shock at a rate of 3 tablespoons per 500 gallons of water

Once a week

- Test Ph, Alkalinity, and Chlorine
- Add 1-2 oz. of Stain & Scale Control
- Add Bioguard Enhanced Shock at a rate of 3 tablespoons per 500 gallons of water

Every 4 months

- Drain and refill your spa
- Replace MicroClean filter

As Needed

- If water looks hazy and test results are all correct add an additional dose of Enhanced Shock and/ or bring a water sample to Tredway Pools for water analysis

North
8301 Lima Rd.
Fort Wayne, IN 46818

(260)489-5596
Fax: (260)489-2714
www.Tredwaypools.com
E-Mail: Service@tredwaypools.com

Southwest
6410W. Jefferson Blvd, Suite 15a
Fort Wayne, IN 46804